Measurement Error: NO012 - Bishop Auckland MTA

Downstream Transporter: Northern Gas Networks

Materiality: Low

Documentation at: http://www.gasgovernance.co.uk/mer/no012

Status: Closed no reconciliation

Dear Colleague,

Please note that, in respect of Measurement Error NO012 - Bishop Auckland MTA, the Downstream Transporter has concluded that no reconciliation is required and has closed the investigation.

Regards,

Helen Cuin Joint Office of Gas Transporters

Tel: 0121 288 2107

Email: enquiries@gasgovernance.co.uk

UNC related documents can be accessed via our

website: www.gasgovernance.co.uk

The information in this E-Mail is confidential and may be legally privileged. It may not represent the views of the Joint Office of Gas Transporters.

It is intended solely for the addressees. Access to this E-Mail by anyone else is unauthorised. If you are not the intended recipient, any disclosure, copying, distribution or any action taken or omitted to be taken in reliance on it, is prohibited and may be unlawful. Any unauthorised recipient should advise the sender immediately of the error in transmission. Unless specifically stated otherwise, this email (or any attachments to it) is not an offer capable of acceptance or acceptance of an offer and it does not form part of a binding contractual agreement.

This message has been sent to our Measurement Errors mailing list. If you wish to unsubscribe, please <a href="mailto:emailto:

Joint Office of Gas Transporters, Radcliffe House, Blenheim Court, Warwick Road, Solihull B91 2AA