

On 3 Nov 2009, at 13:21, .Box.UKLINK.Manual wrote:

Subject: MP/935/SJB - Implementation of Mod 0250: Gemini Code Contingency arrangements

Colleague, Please be advised that with effect of 1st November 2009, Gemini Contingency Procedures have been updated following the implementation of Mod 250.

The new guidelines are available on the Joint Office web site at:

<http://www.gasgovernance.co.uk/OtherDocs>

Supply Point Administration (SPA) Contingency Guidelines, Invoicing Code Contingency Guidelines and Sites & Meters Code Contingency Guidelines are under review and at present remain unchanged.

The redundant Gemini Code Contingency Procedures and Proforma's will be removed from UK Link Extranet shortly.

Regards,

Sarah Blewer Account Officer Xoserve 31, Homer Road, Solihull, B91 3LT. 0121 623 2522 sarah.j.blewer@xoserve.com