

National Grid Sub Deduct Meter Arrangements

17th March 2016

Stacey Goldsmith/Becki Winter

National Grid Distribution


UK GAS DISTRIBUTION





High Level Summary

Total Number of Sites Identified	
Network	No. of sub-deduct sites
East Anglia	24
East Midlands	105
London	241
North West	148
West Midlands	441
Total	969



Survey Outcome	
No sub deduct	384
Re-engineered	209
3 rd party adoption	82
Awaiting customer	165
Work planned	129
Total	969



Re-engineered Sites

- We record a site as 're-engineered' when work has taken place to remove the prime and sub meter arrangement, in this instance we receive a 'post completion survey' from our Operations team confirming the new meter arrangement on site.
- We do not complete work on site until the customer has agreed this is how they wish to proceed, this is confirmed when the survey is being carried out or through communication with the project lead within National Grid following completion of the survey.
- Once re-engineering of the meter arrangement has been completed all details are inputted into CMS, this includes MPRN's, MSN, final meter readings and date work was completed.
- Xoserve then manage going forward and communicate to the relevant shipper for the site.



No sub deduct sites

We record a site as ‘no sub deduct’ when:-

- A survey is completed by a National Grid engineer and confirms there is no sub deduct meter arrangement present:
 - Our process for this would be to inform Xoserve that the survey has identified ‘no sub deduct’ present.
- A reconciliation of the Xoserve quarterly prime and sub report against our workbook, where sites are recorded on our workbook but not on Xoserve’s workbook, we seek further information from Xoserve to confirm that there is no prime and sub present, in these cases the site has usually been re-engineered by a third party.



Remaining sites

- 165 sub deduct networks remain 'at risk' due to:
 - Access issues
 - Awaiting customer decision
- Next Steps
 - Issue a letter to the customer requesting access to the property
 - Contact the customer to discuss options further
 - Search Land Registry for building owner details and issue further letters where access or a decision is still not confirmed.
- 129 sub deduct sites are planned in for re-engineering work in 2016/17.